



Safdy Systems

BLOCK DIAGRAM FOR CH4 for DSP



- 1 - Plug in CH4 cable plug
- 2 - Wire CH4 to DC-DC
- 3 - Wire DC-DC(0-1mA) to TX analog
- 4 - Wire DC-DC(-)Pwr to Choke
- 5 - Wire DC-DC(earth) to orange box earth
- 6 - Wire Choke S1/S2 to TX S1/S2
- 7 - Wire TX COM to DC-DC(+)Pwr

Safdy Systems




WIRING DIAGRAM FOR
DC - DC FOR 4-20mA

*Computerised Telemetry
Technologies (Pty) Ltd*

info@compteltech.co.za
www.compteltech.co.za


Safdy Systems



WIRING DIAGRAM FOR CH4
for DC-DC and Choke
for DSP Transmitter

*Computerised Telemetry
Technologies (Pty) Ltd*
ctt@compteltech.co.za
www.compteltech.co.za

Safdy Systems



WIRING DIAGRAM FOR
DC-DC FOR MUX 0-1mA

*Computerised Telemetry
Technologies (Pty) Ltd*

info@compteltech.co.za
www.compteltech.co.za